
Appendix A Historic heritage

The table below contains a summary of all listed buildings and historic monuments within the Parish. It is taken from the website of Historic England (www. historicengland.org.uk), which includes more detailed schedules on the history and building materials of each listed building or historic monument. The locations of each of these sites are shown in Map A1.

Name/	Category	UID	<u>Description</u> (Edited version of formal listing)
Location	-	_	
<u>Haversham</u>			
Wolverton Viaduct	Grade II	1389687	Railway viaduct. Built 1837-8 for the London and Birmingham Railway, engineer Robert Stephenson, widened on the east side 1878-82 by the London and North Western Railway to accommodate two additional lines. Built in red brick in English bond, repaired in blue engineering bricks with red sandstone dressings. Blue engineering brick used throughout in the widened part.
			It is the most impressive of the several viaducts on the line, being taller, more elaborately treated and with wider arches. It was one of the principal landmarks of the first trunk railway and one of the earliest viaducts on this scale.
Parish Church of St Mary	Grade I	1212152	Parish Church. C12 nave, late C12 tower. C13 chancel rebuilt, south aisle C14, but enlarged circa 1340. North aisle of C13 enlarged c1360. C14 south porch. Nave clerestory C15. Coursed rubblestone with limestone dressings lead roofs except to south porch which has old tile roof. South east chapel has C17 straight mullion square head east window. Norman west window with chevron outer order on columns with volute capitals. Tower has 2- light openings within round arch, battlemented parapet. South porch has small east trefoiled window.
			Interior: Chancel arch of chamfered orders, c1325. South nave arcade of 2 chamfered orders, octagonal piers and moulded capitals. East respond has knot corbel. North nave arcade c1360 as south but with moulded label and head stops. In south chapel, piscina with trefoiled ogee heads. C14. 2 niches in nave east wall. North aisle benches, C16 with cut poppy heads to bench ends.
			Stained glass. South aisle, west end window and chancel north side, west window 1496, figures including St. John Baptist. In south chapel east window fragments of figures and cross, C15. East window by J.T. Micklethwaite circa 1890.
Dovecote at Haversham Manor and To South of St Marys Church	Grade II	1115928	Dovecote. Dated 1665. Coursed rubblestone, old tile roof. Square on plan with pyramid roof surmounted by cupola and wrought iron weather vane Doorway in west wall, 3-light oak framed window on south wall, high up. Date stone on north wall, inscribed 'M.T. 1665'. (Maurice Thompson purchased the manor in 1664). Walls lined with stone nest-boxes.
Moated site, fishponds and associated earthworks 150m south- east of Haversham Manor	Schedule	1011300	Despite having suffered some disturbance in the past, the site survives largely intact and is a good example of its class. The central platform contains archaeological evidence relating to the occupation of the island, including the survival of buried structural foundations relating to the buildings that originally stood upon it. Environmental evidence relating to the landscape in which the monument was constructed will survive in the deeper ditch deposits and in the fishponds.
			The moated enclosure is rectangular in shape. The central platform of the moat is raised slightly above the surrounding land surface. The interior

			surface of the platform is disturbed and uneven particularly in the northern half indicating the survival of sub-surface building remains.
			In the south-western corner of the platform, separated from the edge of the moat by a narrow bank, is a rectangular hollow Its close proximity to the edge of the moat suggests that it is likely to be the remains of a small fishpond.
			To the east of the moated enclosure a recently constructed lake approaches to within 50m of the moat edge; in the area between are the truncated remains of fragmentary banks and hollows which are thought to represent the remains of village cross or garden plots.
			A roughly rectangular hollow which lies adjacent to the north-eastern corner of the moat may represent the remains of a second early fishpond. To the east of the moat some 60m upslope is a large fishpond which appears later in date. A second smaller pond of similar age lies to the north.
The Old Rectory	Grade II	1320193	Former Rectory, now house. Early C18 with 1861-1862 north range. C18 elevations red brick with flared headers. Victorian range red and orange brick. Old tile roofs. 5 bays, 2 storeys plus dormers, Victorian range across north and projecting to west to form letter L-plan, 2 storeys plus attic. C18 part has central door and mid C19 Doric porch, 2 sashes to left, bay window to right. 5 sashes to 1st floor with early C18 thick glazing bars. 3 hipped dormers with 2-light casements, flanking stacks of old thin bricks. South front of 2 builds, 2 left bays early C18 with thick upper floor glazing bars to sashes. Interior has mid C19 fireplaces and metal rosettes to cornice friezes in downstairs rooms.
Summerhous e and Walled Garden to North of the Old Rectory	Grade II	1115929	Walls C18 or early C19, summerhouse 1861 to 1862. Walls outer skin coursed limestone inner skin brick. Tiled copings. Summerhouse brick and slated roof. Walls round three sides of square to north of Old Rectory with summerhouse in centre of north wall. Gabled front with arched centre door flanked by windows to form Palladian front cogged eaves to open pediment.
Pike's Farm	Grade II	1320194	C18, altered. Coursed rubblestone, slate roofs. 5 bays, 2 storey plus dormers, with 2 rear wings at right angles, both of two storeys and late C18 or early C19. South east front has central entry with 6 panel door, rectangular fanlight and panelled reveals. To south west gable of main block is french door with margin panes. Britannia fire insurance plaque on right hand gable.
Haversham Grange	Grade II*	1212158	House, in C14 grange to Lavendon Abbey. C14 with crossing rebuilt 1628, C16, C19 alterations. Coursed rubblestone with dressing. Old tile roofs. 2 bay medieval hall house with raised cruck, cross passage and rebuilt cross wing. 2 storeys plus attics. C16 chimney stack inserted backing onto cross passage and floor inserted in open hall. C19 service building and south lateral stack in chequered brick.
			West elevation has deeply moulded C14 doorway with hood mould on carved heads, diamond window over. 1st floor has to left bay of hall range, gabled window with coped gable on kneelers and small gable window above. North gable coped on kneelers and carved finial, also datestone 'TTE 1628'. South stack stepped and panelled. Tracescfhall window to left of C14 doorway. Hall window complete to rear: North east range. C18 with outside steps to hayloft, south east wing C19 slate roofed.
			Interior: An important example of C14 domestic architecture. Screen passage beyond C14 door has 2 arched openings, one half-blocked, mouldings similar to outer door, then to left timber doorway arch, probably also contemporary. C16 inserted stack backs onto cross passage. Hall truss has raised crucks with arch braced Collar and kingpost. Crucks have wide yoke. Long curved purlin braces.

Hill Farmhouse	Grade II	1289663	Early C19. Coursed rubblestone, slate roofs. 2 storeys, 4 bays, double pile house. North front cement rendered pilastered and corniced entrance in bay 2, panelled reveals, panelled doo. Some windows have cement gauged flat arches with keystones. 3 first floor sashes to bays one to 3. Stacks flank entry bay. South east or garden front has 2 bay windows, sashes above.
<u>Little Linford</u>			
Hall Farm	Grade II	1212150	Farmhouse. C17, C18 and C19. Coursed rubblestone, south elevation part brick. Plain roof tiles. 4 bay south front, left hand bay extending north to form letter-L plan. 2 storeys. South front. 3 left hand bays stone, right hand bay chequer brick. Bay window to outer bays, blocked door to second bay from left, triparite sash to third. 1st floor sashes. North elevation with west wing roof extended eaves and modern dormer. Central door with stone architraved and pedimented doorcase.
			Interior has features salvaged from Little Linford Hall including doorcases with lugged architrave surrounds and overdoors; friezes and cornices with wave mould and egg-and-dart friezes. Also chimney pieces. These are described in RCHM II. 179 MON. 2, Linford hall and dated to late C17.
Gate Piers and Gates to West of Linford Hall	Grade II	1115927	Gate piers. Mid C19, formerly to Linford Hall, now demolished. (The present house is a modern one). Cast iron piers and wrought iron gates. Short lengths of railing to each side of piers. Piers hollow square sections, chamfered sides with bases. Corniced caps with ogee saddleback tops. Scroll tops to gates.
Church of St Leonard and St Andrew	Grade II*	1212140	Parish church. Early C13. South aisle C14, rebuilt c18 or C19. Chancel and north aisle rebuilt Cl9. Rubblestone with limestone dressings. Old tile roof. 2 bay chancel with reused C13 lancet windows. Nave without clerestory. South aisle has C13 doorway, reset, with nail-head enrichment and C14 2 light tracered windows and one 3-light square headed C16 window. West window 3-light 4 centred head. North aisle has C14 2-light tracered windows. West gable has C13 gabled bellcote with 2 arched openings for bells, the jambs and central mullion having attached shafts. C19 north porch.
			Interior: north arcade C13, 2 bays with chamfered orders and moulded octagonal capital to cylindrical column. South Arcade of nave 3 bays also with octagonal moulded capitals and octagonal columns. Font of tub type on square chamfered base, C13. Plaster ceiling to nave with moulded wall plate and curved braces to wall posts. Cambered tiebeams. C15. Chancel arch reponds C13 arch C19. Wall tablets: In chancel 2 ovals with carved wreath surrounds to Sophia Knapp 1795, and Matthew Knapp, 1787. Other C18 and C19 tablets to Knapp family.
Stanton Low			
Ruins of Church of St Peter	Grade II	1125226	Ruins of former parish church. Norman and CI5, restored early C20 but now a fragmentary ruin. Rubble limestone, walls only. The E. wall of the chancel almost complete, with the arch of a C14 window.



Map A1 Listed buildings and scheduled monuments


Appendix B



Extract of MKC Interactive mapping showing the extent of Archaeological Notification Sites in part of the parish

Appendix C

Local Areas of Special Character



Haversham-cum-Little Linford Neighboughood Plan Policies Map

December 2021

Key

Parish Boundary


HLL6 - Non-designated heritage assets ii. Land at Haversham Mill

HLL8 - Existing footpaths and bridleways (also part of HLL9)

HLL9 - Existing green and blue infrastructure network

HLL9 - Opportunity wildlife corridor

HLL10 - Important views



Ordnance Survey, (c) Crown Copyright 2020. All rights reserved. Licence number 100022432